

Ransom Township MS4 Outfalls

Outfall # & Name	Lat.	Long	Pipe Size	Pipe Material	Discharge to
1 Lookout & Division	41D 25.570	75D 42.835	15"	HDPE	Lindy Creek
2 Division St.	41D 25.599	75D 42.894	15"	HDPE	Lindy Creek
3 Division St. @ S	41D 25.598	75D 42.933	15"	HDPE	Lindy Creek
4 Division St.	41D 25.643	75D 43.068	15"	HDPE	Lindy Creek
5 Division St.	41D 25.678	75D 43.133	15"	HDPE	Lindy Creek
6 Community Dr.	41D 25.787	75D 43.166	15"	HDPE	Lindy Creek
7 Community Dr.	41D 25.835	75D 43.147	15"	HDPE	Lindy Creek
8 Community Dr.	41D 25.885	75D 43.130	15"	HDPE	Lindy Creek
9 Lookout @ Gates'	41D 25.599	75D 43.135	15"	HDPE	Lindy Creek
10 Lookout @ bottom	41D 25.493	75D 42.923	15"	HDPE	Lindy Creek